L	Hits	Search Text	DB	Time stamp
Number 13	7816	((measure measuring measured measurement	USPAT;	2004/05/13
	, , , ,	meter metering) with distance) and	US-PGPUB;	15:50
		((change changing vary varying adjust	EPO; JPO;	
		adjusting adjustment correct correcting	DERWENT;	
		correction) with (laser light beam) with	IBM_TDB	
		(power intensity intensities))		
14	1123	((measure measuring measured measurement	USPAT;	2004/05/13
<u> </u>		meter metering) with distance) same	US-PGPUB;	15:22
		((change changing vary varying adjust adjusting adjustment correct correcting	EPO; JPO; DERWENT;	
		correction) with (laser light beam) with	IBM TDB	
		(power intensity intensities))	15155	
15	730	((measure measuring measured measurement	USPAT;	2004/05/13
		meter metering) with distance) with	US-PGPUB;	15:22
1		((change changing vary varying adjust	EPO; JPO;	
		adjusting adjustment correct correcting	DERWENT;	
		correction) with (laser light beam) with	IBM_TDB	
1.6	4571	(power intensity intensities))	HCDAT.	2004/05/13
16	4571	((measure measuring measured measurement meter metering) with distance) and	USPAT; US-PGPUB;	15:28
		((change changing vary varying adjust	EPO; JPO;	13.20
		adjusting adjustment correct correcting	DERWENT;	
		correction) with (laser light beam) with	IBM TDB	
		(power intensity intensities)) and (print	_	
		printing printer image imaging)		
17	1859	((measure measuring measured measurement	USPAT;	2004/05/13
		meter) with distance) and ((vary varying)	US-PGPUB;	15:24
		with (laser light beam) with (power	EPO; JPO;	
		intensity intensities)) and (print printing printer image imaging)	DERWENT;	
18	412	((measure measuring measured measurement	USPAT;	2004/05/13
10	712	meter metering) with distance) with	US-PGPUB;	16:09
	, 1.	((change changing vary varying adjust	EPO; JPO;	
		adjusting adjustment correct correcting	DERWENT;	
	.	correction) with (laser light beam) with	IBM_TDB	
	:	(power intensity intensities)) and (print		
1.0	216	printing printer image imaging)	HEDAT.	2004/05/13
19	216	((measure measuring measured measurement meter metering) with distance) same	USPAT; US-PGPUB;	15:24
		((change changing vary varying adjust	EPO; JPO;	13.24
		adjusting adjustment correct correcting	DERWENT;	
		correction) with (laser light beam) with	IBM_TDB	
		(power intensity intensities)) same	-	
		(print printing printer image imaging)	1	0004/07/50
20	115	((measure measuring measured measurement	USPAT;	2004/05/13
		meter metering) with distance) with	US-PGPUB;	15:25
		((change changing vary varying adjust adjusting adjustment correct correcting	EPO; JPO; DERWENT;	
		correction) with (laser light beam) with	IBM TDB	
		(power intensity intensities)) with		
		(print printing printer image imaging)		
21	48846	distance with (light laser beam) with	USPAT;	2004/05/13
		(drum ((print printing imaging image)	US-PGPUB;	15:26
		surface))	EPO; JPO;	
,	1		DERWENT;	
33	1020	///mangura manguring mangured mangurement	IBM_TDB USPAT;	2004/05/13
22	1839	(((measure measuring measured measurement meter metering) with distance) and	US-PGPUB;	15:26
	1	((change changing vary varying adjust	EPO; JPO;	
		adjusting adjustment correct correcting	DERWENT;	
	1	correction) with (laser light beam) with	IBM_TDB	
		(power intensity intensities)) and (print	_	
	1	printing printer image imaging)) and	1	
		(distance with (light laser beam) with		
		(drum ((print printing imaging image)		
	L	surface)))	I	

	0.7		IICDAM.	2004/05/13
23	27	((measure measuring measured measurement	USPAT;	16:02
		meter metering) with (laser light beam)	US-PGPUB;	16.02
		with (print printing imaging image) with	EPO; JPO;	
		distance) and ((change changing vary	DERWENT;	
		varying adjust adjusting adjustment	IBM_TDB	
		correct correcting correction) with		
		(laser light beam) with input with (power		
		intensity intensities)) and (print		
2.4	7	<pre>printing printer image imaging) ((measure measuring measured measurement</pre>	USPAT;	2004/05/13
24	l '	meter metering) with (laser light beam)	US-PGPUB;	15:49
		with (print printing imaging image) with	EPO; JPO;	10.15
		distance) same ((change changing vary	DERWENT;	
		varying adjust adjusting adjustment	IBM TDB	
		correct correcting correction) with	15155	
		(laser light beam) with input with (power		
		intensity intensities)) same (print		
		printing printer image imaging)		
27	0		USPAT;	2004/05/13
27	"	meter metering) with (laser light beam)	US-PGPUB;	15:50
		with (print printing imaging image) with	EPO; JPO;	20.00
		distance) same ((change changing vary	DERWENT;	
ļ		varying adjust adjusting adjustment	IBM TDB	
		correct correcting correction with		
	1	(laser light beam) with input with (power		
		intensity intensities)) same (print		
		printing printer image imaging)) and		
	ĺ	(distance with meter)		
28	612	(((measure measuring measured measurement	USPAT;	2004/05/13
20	""	meter metering) with distance) and	US-PGPUB;	15:50
		((change changing vary varying adjust	EPO; JPO;	
	1	adjusting adjustment correct correcting	DERWENT;	
		correction) with (laser light beam) with	IBM TDB	1
		(power intensity intensities)) and (print	_	
		printing printer image imaging)) and		
		(distance with meter)		
29	1902	((meter metering) with distance) and	USPAT;	2004/05/13
		((change changing vary varying adjust	US-PGPUB;	15:51
		adjusting adjustment correct correcting	EPO; JPO;	
		correction) with (laser light beam) with	DERWENT;	
		(power intensity intensities))	IBM_TDB	
30	206	((meter metering) with distance) and	USPAT;	2004/05/13
		(((change changing vary varying adjust	US-PGPUB;	15:51
		adjusting adjustment correct correcting	EPO; JPO;	
		correction) with (laser light beam) with	DERWENT;	
		(power intensity intensities)) with	IBM_TDB	
		distance)	TIGDAE:	2004/05/13
31	31	((meter metering) with distance) with	USPAT;	15:55
		(((change changing vary varying adjust	US-PGPUB;	13.33
1		adjusting adjustment correct correcting	EPO; JPO;	·
1	1	correction) with (laser light beam) with	DERWENT;	
		(power intensity intensities)) with	IBM_TDB	
		distance) ((meter metering) with distance) with	USPAT;	2004/05/13
32	2	((meter metering) with distance) with (((change changing vary varying adjust	US-PGPUB;	15:52
		adjusting adjustment correct correcting	EPO; JPO;	1 20.02
		correction) near (laser light beam) with	DERWENT;	[
		(power intensity intensities)) with	IBM TDB	<u> </u>
		(power Intensity Intensities); with distance)		
33	1	1	USPAT;	2004/05/13
"	1	(laser light beam) with (drum ((print	US-PGPUB;	15:56
		printing imaging image photosensitive)	EPO; JPO;	
		with surface))) with (((change changing	DERWENT;	
		vary varying adjust adjusting adjustment	IBM TDB	
		correct correcting correction) with	-	
		(laser light beam) with (power intensity		
		intensities)) with distance)		l
		· · · · · · · · · · · · · · · · · · ·		

	, .		HORRE	2004/05/12
35	2	((meter metering) with distance with (laser light beam) with (drum ((print printing imaging image photosensitive) with surface))) and (((change changing vary varying adjust adjusting adjustment correct correcting correction) with (laser light beam) with (power intensity intensities)) with distance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13
36	10	((measure measuring measured measurement meter metering) with (laser light beam) with (print printing imaging image) with distance) and ((change changing vary varying adjust adjusting adjustment correct correcting correction) with (laser light beam) with input with (power intensity intensities) with distance) and (print printing printer image imaging)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13
37	1	((measure measuring measured measurement meter metering) with (laser light beam) with (print printing imaging image) with distance) and ((change changing vary varying adjust adjusting adjustment correct correcting correction) with (laser light beam) with input with (power intensity intensities)) and (print printing printer image imaging)) and (distance with meter)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13 16:03
38	22	(((measure measuring measured measurement meter metering) with distance) same ((change changing vary varying adjust adjusting adjustment correct correcting correction) with (laser light beam) with (power intensity intensities)) same (print printing printer image imaging)) and (distance with meter)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13 16:08
39	152	bernd with vosseler) (bernard with beier) (uwe with ernst	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13 16:08
40	193904	((measure measuring measured measurement meter metering) with distance)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13
41		(bernd with vosseler) (bernard with beier) (uwe with ernst) and (((measure measuring measured measurement meter metering) with distance))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13 16:14
44	401727	<pre>((measure measuring measured measurement meter metering) with (position distance))</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13
45	13	beier) (uwe with ernst) and (((measure measuring measured measurement meter metering) with (position distance)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13
46	1	<pre>((bernd with vosseler) (bernard with beier) (uwe with ernst) and (((measure measuring measured measurement meter metering) with (position distance)))) not(((bernd with vosseler) (bernard with beier) (uwe with ernst) and (((measure measuring measured measurement meter metering) with distance))))</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/13

47	13	(bernd with vosseler) (bernard with	USPAT;	2004/05/13
		beier) (uwe with ernst) and (((measure	US-PGPUB;	16:15
		measuring measured measurement meter	EPO; JPO;	
		metering) with (position distance)))	DERWENT;	
			IBM TDB	